

# Tolerances for Lathe Cut Washers & Rings

## OUTSIDE DIAMETER

WALL (INCHES)		TOLERANCE*
ABOVE	INCLUDED	(INCHES)
.030	.200	+/- .008
.200	.300	+/- .012
.300	& over	+/- .015


\* Measured on fixed mandrel

## INSIDE DIAMETER

INSIDE DIAMETER (INCHES)		TOLERANCE**
ABOVE	INCLUDED	(INCHES)
.200	.700	+/- .007
.700	1.500	+/- .010
1.500	2.600	+/- .010
2.600	5.000	+/- .025
5.000	7.500	+/- .035
7.500	9.000	+/- .060
9.000	12.000	+/- .075

## THICKNESS

CUT (INCHES)		TOLERANCE
ABOVE	INCLUDED	(INCHES)
.015	.200	+/- .005
.200	.400	+/- .010
.400	.500	+/- .015
.500	.600	+/- .020
.600	.700	+/- .025
.700	1.000	+/- .030



RubberMill

**Disclaimer:** The information contained in this document is to be used as a guide only. RubberMill cannot guarantee the accuracy, or be held responsible for the information's end use.

Talk to a Person, Not a Machine! · 336-622-1680 · [www.RubberMill.com](http://www.RubberMill.com)